





Structurally Deficient Bridges on the National Highway System Tennessee - Congressional District 04



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 74 structurally deficient NHS bridges in Tennessee, 12 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	60I00650010	I65	6 M N MARSHALL CO LINE
2	31I00240003	I24	1.5 MI SOUTH OF SR50
3	31I00240004	I24	1.5 MI SOUTH OF SR50
4	31I00240006	I24	2 MI SOUTH OF SR50
5	31I00240005	I24	2 MI SOUTH OF SR50
6	73I00400002	I40	NEAR HARRIMAN (WEST)
7	65SR0290031	FAP 29	5.22 MI.S.OF SCOTT CO.
8	07I00750018	I75	11.29M.FROM ANDERSON CO.L
9	07I00750017	I75	11.29M FROM ANDERSON CO.L
10	07I00750013	I75	5.64 M.FROM ANDERSON CO.L